



INSTALLATION INSTRUCTIONS 6 X 10 CENTER LOCK ELECTRIC STRIKE DLEL610BS, DLEL610PB, DLEL610PS, DLEL610SC DLER610BS, DLER610PB, DLER610PS, DLER610SC













PRE-WIRE ELECTRIC STRIKE PER ENCLOSED INSTRUCTIONS









ASSEMBLE CLAMP PLATES ONTO GLASS. BE SURE TO HAVE NUTS AND WASHERS ON THE OUTSIDE




RE-INSTALL ELECTRIC STRIKE TEST FOR ALLIGNMENT WITH LOCK COMPLETE WIREING CHECK STRIKE OPERATION



REMOVE VHB TAPE COVER PAPER APPLY COVER PLATES PRESS FIRMLY TO ENSURE ADHESION



RE-ATTACH STRIKE PLATE



CHECK STRIKE OPERATION