



Underwriters Laboratories Inc.®

1655 Scott Boulevard  
Santa Clara, California 95050-4169  
United States Country Code (1)  
(408) 985-2400  
FAX No. (408) 296-3256  
<http://www.ul.com>

SA12817, 03SC04383

March 21, 2003

C.R. Laurence Co., Inc.  
Gardena, CA

Fax No: 1-310-515-1257

Attention: Mr. Gary Sprague

Reference: File SA12817, Vol. 1, Sec. 1

Subject: Series EG100 and EG110 Electronic Egress Handles

Dear Mr. Gary Sprague:

**NOTICE OF AUTHORIZATION TO APPLY THE UL MARK**

UL's investigation of your products has been completed under project number 03SC04383 and the products were determined to comply with the applicable requirements.

This fax temporarily supplements the UL Follow-Up Services Inspection Procedure and serves as authorization to apply the UL Recognized Marking and/or Recognized Component Mark only at the factory under UL's Follow-Up Service Program to the above products which are constructed as described below:

Similar to products covered in the UL Follow-Up Services Inspection Procedure, File SA12817, Vol. 1, Sec. 1.

Modified as follows: Series EG100 and EG110 are identical to currently Recognized Series EG, except for designation.

To provide the manufacturer with the intended authorization to use the UL Mark, the addressee must send a copy of this Notice and all attached material to each manufacturing location as currently authorized in File SA12817, Vol. 1.

SA12817, 03SC04383  
March 21, 2003  
Page 2

This authorization is effective for 90 days from the date of this Notice and only for products at the indicated manufacturing locations. Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent to the indicated manufacturing locations in the near future. Please note that the Follow-Up Services Procedures are sent to the manufacturers only unless the Applicant specifically requests this document.

Products which bear the UL Mark shall be identical to those which were evaluated by UL and found to comply with UL's requirements.

If changes in construction are discovered, authorization to use the UL Mark may be withdrawn and products that bear the UL Mark may have to be revised (in the field or at the manufacturer's facility) to bring them into compliance with UL's requirements.

Regards,

Reviewed by:



NATHAN JAMISON (Ext. 32316)  
Associate Project Engineer  
Conformity Assessment Services  
Section 3013D



MICHAEL FUNG (Ext. 32158)  
Engineering Team Leader  
Conformity Assessment Services  
Section 3013D